

Sunday	Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	
MAY 2008 S M T W T F S 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31		<h1>June 2008</h1>				JULY 2008 S M T W T F S 1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31	
1 153/213 MD99 2004 MD15 2004 WV99 2000 MD99 2004	2 154/212	3 Week 23 NTN and AIRMoN Reminder: Change dry side bucket and clean foam lid seal. MT05 1980 W137 1980 GA09 1997 ME02 1997	4 156/210	5 157/209 WY08 1980 CO02 1984 TX22 1984 WI99 1984 AL02 2001 AL02 2001	6 158/208	7 159/207 PA15 1983 WI10 2005	
8 160/206	9 161/205	10 Week 24 NY10 1980 NY52 1980	11 163/203	12 164/202 VT99 1984 ME95 2002	13 165/201 GA40 2000 CA96 2000	14 166/200	
15 167/199	16 168/198 MS22 2000	17 Week 25 AK03 1980 FL11 1980	18 170/196 TX02 1985	19 171/195	20 172/194 AL03 2000 PA30 2000	21 173/193	
22 174/192 NM07 1982 AK02 2004	23 175/191	24 Week 26	25 177/189 CA76 1985	26 178/188 NE15 2007 WV99 2007 MI26 1979 TX16 1984	27 179/187	28 180/186	
29 181/185 TX21 1982 WI28 1982 MD08 2004	30 182/184			<p>"I had some minor bear problems this week. The W/D collector got tipped over. I repaired the stand/collector, cleaned lid pad, checked for level, and checked that the lid is sealing on both buckets. The current problem is the support arm for the sensor got snapped off at the base. I have it firmly supported right now and it works fine." - MI99 NTN Operator</p>			