





May 2003

| Sunday | Monday | Tuesday | Wednesday | Thursday | Friday | Saturday |
|---|--|--|-------------------|-------------------|-------------------|-------------------|
|  <p>Questions? Call the CAL at 1-800-952-7353 or visit http://nadp.sws.uiuc.edu/cal/</p> | | | | 1 121/244 | 2 122/243 | 3 123/242 |
| 4 124/241 | 5 125/240 | 6  126/239 Change dry side bucket and clean foam lid seal | 7 127/238 | 8 128/237 | 9 129/236 | 10 130/235 |
| 11 131/234  Mother's Day | 12 132/233 | 13 133/232 | 14 134/231 | 15 135/230 | 16 136/229 | 17 137/228 |
| 18 138/227 | 19 139/226 | 20 140/225 | 21 141/224 | 22 142/223 | 23 143/222 | 24 144/221 |
| 25 145/220 | 26 146/219  Memorial Day | 27 147/218 | 28 148/217 | 29 149/216 | 30 150/215 | 31 151/214 |

May 17, 1983 - A golfer playing the Fox Meadows course in Memphis, Tennessee, was struck by a bolt of lightning that went through his neck, down his spine, came out a pocket containing his keys, and went into a nearby tree. Miraculously, he survived!
Source: www.intellicast.com

Reminder: By now, most sites are no longer receiving frozen precipitation. If this is true at your site, the funnel should be reinstalled in the raingage and the antifreeze removed from the bucket. Please note the date of de-winterization in the remarks block of the FORF (Block 10). Call the CAL if you have questions about winterizing procedures at your site.